



# QUOTATION

Quote No. 38646

**Baja Window Shading S. de R.L. de C.V.**  
Cinco de Mayo, # 230-A  
Col. Crosthwaite, C.P.22710  
Playas de Rosarito, B.C., México.  
Mex. Phone: +52 (661) 612-6988  
USA Phone: 1 (702) 842-4044 X 112


**Billing Information**  
Di Calabria Industries Inc.  
9927 Via de la Amistad  
San Diego, CA 92154  
Contact: Yuki Peralta  
Phone: (619) 941-2700

**US Receiving and Shipping Warehouse**  
Ruffo de Alba Forwarders, LP  
9927 Via de la Amistad Business Park  
San Diego, CA 92154  
Contact: Ricardo Montes  
Phone: (619) 591-9391

TO: KONI HOSPITALITY  
Contact: CAROLINE KANG

Today's Date: 14-Jan-25  
Quote valid until: 15-Mar-25

Project Name: LANDRY'S LAGUNA BEACH  
Project Location: \_\_\_\_\_

Item	Qty	UOM	Description	Face Yds. Req. Each	I.D. Window and/or Area	Rod Size	Finished Length	Price EA	Total
1	1	PNL	RIPPLEFOLD SHEER DRAPERY (BATON OPERATED)	14.10	SLN 501 WT	187.000	101.000	\$ 97.80	\$ 97.80
	1	PNL	SIZES: SEE COLUMNS FOR SIZES	14.10	SLN 501 WT	186.000	101.000	\$ 97.80	\$ 97.80
	1	STAT.	STYLE: RIPPLEFOLD @ 220 % FULLNESS. 1.5 INCHES HEAD SIZE.	5.50	SLN 500 WT	67.000	101.000	\$ 40.20	\$ 40.20
			HEMS: BLINDSTITCHED HEMS. 4 INCHES SINGLE BOTTOM HEMS, 1.5 INCHES DOUBLE SIDE HEMS. WITH LEAD WEIGHTS AT CORNERS & SEAMS.						
			MOUNT: CEILING MOUNT						
			HARDWARE: SEE ITEM No.3						
			CONTROL: SEE ITEM No.3						
			FABRIC: C.O.M. / REID WITLIN / MONARCH / OATMEAL / 118 GOODS	COM TOTAL FABRIC YDS. REQ. = 35					
			TASSELS: COM / SAMUEL & SONS SC-95602 AURELIA SINGLE TASSEL TIEBACK						
						Total Item 1=		\$	193.60
2	1	EA.	ASSEMBLED TRACKS FOR RIPPLEFOLD SHEER DRAPERIES	OPERABLE	SLN 501 WT	187.000		\$ 296.40	\$ 296.40
	1	EA.	MOUNT: CEILING MOUNT	OPERABLE	SLN 501 WT	186.000		\$ 296.00	\$ 296.00
	1	EA.	HARDWARE: EXTRUDED ALUMINUM ARCHITECTURAL ASSEMBLED UNI TRACK, POWDER COATED WHITE ATTACHED TO A HALF WOOD POLE	STATIONARY	SLN 500 WT	67.000		\$ 127.00	\$ 127.00
			CONTROL: 36" WHITE BATONS FOR OPERABLE DRAPES						
			POLE: 2" DIAMETER SMOOTH WOOD POLE, PAINTED TBD.						
									
						Total Item 2=		\$	719.40
8	1	EA.	1 TRIP AND TAKING OF MEASURES TO 3 OPENNINGS.					\$ 880.00	\$ 880.00
9	1	EA.	1 TRIP AND INSTALLATION 3 SHEER DRAPERIES WITH DECO HARDWARE					\$ 1,620.00	\$ 1,620.00

PRICES ARE FOB SAN DIEGO, PACKAGING INCLUDED. DUTIES ARE INCLUDED.

LEAD TIME 4-6 WEEKS AFTER RECEIVING P.O., PREPAYMENT AND C.O.M. FABRICS.

**PAYMENTS TERMS:** 50% PREPAYMENT + 50% BALANCE NET 15 DAYS.

**LATE FEES:** 5% MONTHLY INTEREST FOR 30-60 DAYS. 8% MONTHLY INTEREST FOR 60-90 DAYS AND 12% MONTHLY INTEREST FOR 90-120 DAYS

Measurement Charges are based on take measures during 1 working days if Rooms and/or areas are accessible all time.

Downtime fee per Measure Technician is \$250.00 per day.

Prices are based on full a full availability of rooms based on 2 persons installing during 1 working day.

Down time fee is \$250 dls. per day per installer. Additional Trip for Installation \$ 850 per Installer.

**LODGING NOT INCLUDED. TO BE PROVIDED BY PROPERTY , OR TO BE REIMBURSED.**

ADD \$70 cents per Linear Foot for Installation on Concrete.

**IF SCISSOR LIFT OR SCAFFOLDING ARE REQUIRED IT NEEDS TO BE PROVIDED BY GENERAL CONTRACTOR OR PROPERTY.**

**COM FABRICS:** BWS will not be responsible or liable for any shrinkage, discoloration, defects or other issues associated with or relating to the use of Customer's Own Materials and will only warrant workmanship as it does not apply to COM.

Fabrics swatches must be submitted with purchase order identifying the corresponding product, face and direction pattern is to be applied to product. BWS will not begin production until swatches and information

has been received. Yardages are estimated based upon sizes and specifications provided. BWS will not be responsible for any additional fabrics/trims required.

Excess COM will be shipped to the property with the order upon completion of the project unless otherwise specified in writing.

**Silk Fabrics / Taffetas and Other Specialty Fabrics :** When sewing silk fabrics and taffetas, there is a tendency for creasing/puckering which is inherent to the fabric and cannot be avoided or removed by methods such as steaming.

Quoted by: Abel Salazar

**GRAND TOTAL= \$ 3,413.00**