

Shelley Franklin

From: Brian Watson <brianwatson035@gmail.com>
Sent: Thursday, September 25, 2025 12:18 PM
To: niesel@shalimar.com
Cc: Shelley Franklin; triehm@studioajo.com; Jonathan Marcinkowski
Subject: Shalimar Beach Sanibel owners walk on stack preference

Follow Up Flag: Follow up
Flag Status: Flagged



All,

Walked the entire property with the owner and below is what he called as the correct stack positions. I have listed the current unit numbers, the numbers in () are what we used on the measure trip and the current stack position. (good) notes everything is ok as is, (currently) is what the stack position is and the new stack position stated after currently. Additionally the owner is also interested in the possibility of universal stacks. Masters and batons on each end, no returns

101 (211) R good
102 (210) L currently R
103 (209) R good
105 (207) R good
106 (206) L currently R
107 (205) R good
108 (204) R good
109 (203) R good
110 (202) L currently R
111 (201) L currently R
211 (301) L currently R
210 (302) L currently R40
209 (303) R good
208 (304) R good
207 (305) R good
206 (306) L currently R
205 (307) L currently R
204 (308) R good
203 (309) L currently R
202 (310) L currently R
201 (311) R good

Villas
301 (1N) R good
302 (1S) L currently R
303 (2S) R good
304 (2N) L currently R
305 (3N) R good
306 (3S) L currently R
307 (4N) R good
308 (4S) L currently R

402 (5N 2nd fl) R good
404 (5S 2nd fl) L currently R
401 (5N 1st fl) R good
403 (5S 1st fl) L currently R

Best Regards,

Brian