



301a Enterprise St
Ocoee, Florida, 34761

Tel/Fax: 407-295-5200 Orlando 321-622-8909 Melbo
Email:
Website: www.VUWindowTreatments.com


Order Confirmation

| |
|--------------------|
| Job Number |
| VU500030 |
| Account Number |
| NGUY1003 |
| Order Date |
| |
| Sales Person |
| Ahren |
| |
| Customer Reference |
| |

| | |
|------------|---|
| Invoice To | Mrs. Ban Nguyen, 3310 W North B St, Tampa, FL, 33609 8132989045 dong_mh@hotmail.com |
|------------|---|

| | |
|------------|---|
| Deliver To | Mrs. Ban Nguyen, 3310 W North B St, Tampa, FL, 33609 8132989045 dong_mh@hotmail.com |
|------------|---|

| # | Location | Product | Description | Qty | Net | Total |
|---|----------|-----------------------------------|--|-----|---------|----------|
| 1 | Master | Shutter | Mirasol Fauxwood, Master, Window Opening, L Frame 8723, 3 with Sill Plate, Inside, 108 7/8 inch, 69 1/8 inch, White, 3 1/2 inch, Hidden Tilt, 3 Panels LTRTR, Divider Rail Center, TPOST 36 73 1\8 | 1 | 1946.30 | 1,946.30 |
| 2 | Loft | Shutter | Mirasol Fauxwood, Loft, Window Opening, L Frame 8723, 3 with Sill Plate, Inside, 69 3/4 inch, 45 7/8 inch, White, 3 1/2 inch, Hidden Tilt, 4 Panels LLRR, Divider Rail Center | 1 | 758.52 | 758.52 |
| 3 | Loft w2 | Shutter | Mirasol Fauxwood, Loft w2, Window Opening, L Frame 8723, 3 with Sill Plate, Inside, 69 3/4 inch, 45 7/8 inch, White, 3 1/2 inch, Hidden Tilt, 4 Panels LLRR, Divider Rail Center | 1 | 758.52 | 758.52 |
| 4 | | FREE INSTALLATION!! (\$185 Value) | FREE INSTALLATION!! (\$185 Value) | 1 | 0.00 | |



Customer Message

***This is a custom order in which the order should be paid in full to begin production. A deposit is required. The final payment will be due at installation. If the installation is not completed due to a service or missing product, you may pay 40% of the balance, and the final 10% on completion.

***Customer to remove old window treatments or other obstacles prior to installation. Any previous arrangements must be noted on this order. All free hanging verticals do not close tight. A view into the room is possible on an angle. 2" Horizontal blinds do not close tight. Light gapping will occur. This is the nature of the blind. Room darkening shades are not blackout shades unless side channels are added. With side channels there is still a possibility of light leakage.

***No specific time of day can be promised for delivery. It is the policy of VU Window Treatments to deliver all items as quickly as possible. Unfortunately we are dependent upon our suppliers to help us meet anticipated delivery dates. Our promise of delivery is based upon deliveries to us, therefore subject to revision due to the above factors.

THIS IS A CUSTOM ORDER AND IS NOT SUBJECT TO CANCELLATION. Changes must be made within 3 days of deposit.

Discount: \$519.50

Subtotal: \$2,943.84

Sales Tax: \$250.23

Total: \$3,194.07

Payments: \$1,500.00

Balance Due: \$1,694.07

Payment Type: Deposit-Visa

Installed by: _____ Date: _____

Remittance Advice

Customer: Mrs. Ban Nguyen

Job Number: VU500030

Order Date: 02-21-2023

Total Due: \$1,694.07

Paid: \$

Please detach and send with payment to:

VU Window Treatments
301a Enterprise St
Ocoee, Florida, 34761

Signed by Ban Nguyen