



301a Enterprise St
Ocoee, Florida, 34761

Tel/Fax: 407-295-5200 Orlando 321-622-8909 Melbourne
Email:
Website: www.VUWindowTreatments.com

Quotation	
Quotation No.	VU500267
Account Number	Downtown District Facilities Management
Date	05-01-2023
Sales Person	Ahren

Quote To	Mrs. Margarita Lopez, Downtown District Facilities Management, 425 N Orange Ave, Orlando, FL, 32801E 407 4024603 Margarita.Lopez@ocfl.net	Deliver To	Capital Projects division 400 E South St 5th Floor Orlando, FL, 32801
-----------------	--	-------------------	--

#	Location	Product	Description	Qty	Net	Total
1	Hellen maill room w1	Mini Blinds	Hellen maill room w1, Mount: Inside, 1 inch Aluminum, 121 Brushed Aluminum, 1 inch Aluminum Customizer, Controls: Standard, Brackets: Standard, Valance: Standard, Valance Returns: NO, 8 Gauge	1	142.26	142.26
2	Hellen maill room w2	Mini Blinds	Hellen maill room w2, Mount: Inside, 1 inch Aluminum, 121 Brushed Aluminum, 1 inch Aluminum Customizer, Controls: Standard, Brackets: Standard, Valance: Standard, Valance Returns: NO, 8 Gauge	1	142.26	142.26
3	Hellen maill room w1	Roller Shades	Hellen maill room w1, Outside Mount, Dream Blackout, Ash, Range 1, 3 inch Flat Fascia, Grey/Aluminum, Tear Drop B/R Grey/Alum, Controls: Clutch Left, Stainless Chain	1	300.14	300.14
4	Hellen maill room w2	Roller Shades	Hellen maill room w2, Outside Mount, Dream Blackout, Ash, Range 1, 3 inch Flat Fascia, Grey/Aluminum, Tear Drop B/R Grey/Alum, Controls: Clutch Right, Stainless Chain	1	300.14	300.14
5	Hellen maill room w1		Hellen maill room w1, Product: Labor / Trip Fee	1	85.00	85.00

Customer Message

***This is a custom order in which a 50% deposit is required to begin production. The final payment will be due at installation. If the installation is not completed due to a service or missing product, you may pay half of the balance, and the final amount on completion.

***Customer to remove old window treatments or other obstacles prior to installation. Any previous arrangements must be noted on this order. All free hanging verticals do not close tight. A view into the room is possible on an angle. 2" Horizontal blinds do not close tight. Light gaping will occur. This is the nature of the blind. Room darkening shades are not blackout shades unless side channels are added. With side channels there is still a possibility of light leakage.

***No specific time of day can be promised for delivery. It is the policy of VU Window Treatments to deliver all items as quickly as possible. Unfortunately we are dependent upon our suppliers to help us meet anticipated delivery dates. Our promise of delivery is based upon deliveries to us, therefore subject to revision due to the above factors.

THIS IS A CUSTOM ORDER AND IS NOT SUBJECT TO CANCELLATION. Changes must be made within 3 days of deposit.

	\$ 0.00
Subtotal:	\$ 969.80
Sales Tax:	\$ 0.00
Total:	\$ 969.80
Deposit :	\$ 0.00
Balance:	\$ 969.80

Remittance Advice

Customer: Mrs. Margarita Lopez
Quotation No: VU500267
Quotation Date: 05-01-2023
Total Due: \$ 969.80
Paid:

Please detach and send with payment to:

VU Window Treatments
301a Enterprise St
Ocoee, Florida, 34761