



301a Enterprise St  
Ocoee, Florida, 34761

Tel/Fax: 407-295-5200 Orlando / 407-292-7691  
Email: 321-622-8909 Melbourne  
Website: www.VUWindowTreatments.com

### Order Confirmation

Job Number
VU501790
Account Number
YERG1001
Order Date
Sales Person
Ahren
Customer Reference

<b>Invoice To</b>	Mr. Bob Yerger, 11031 Galway Isles Ct, Windermere, FL, 34786 5514271076 bobyerger@gmail.com	<b>Deliver To</b>	Mr. Bob Yerger, 11031 Galway Isles Ct, Windermere, FL, 34786 5514271076 bobyerger@gmail.com
-------------------	---	-------------------	---

#	Location	Product	Description	Qty	Net	Total
1	Office	Smart Shutter	VU Window Treatments Office, Frame: Designer OM, 3 with Add Sill Plate, Outside, 51 3/4 inch, 63 inch, White, 3 inch Louvers, Front Tilt, 2 Panels L/R Hinge, Divider Rail +/-, Divider/ Split Location: 32, TAKE DOWNS!!!	1	887.00	887.00
2	M bath	Smart Shutter	VU Window Treatments M bath, Frame: Designer OM, 3 with Add Sill Plate, Outside, 36 3/4 inch, 51 inch, White, 3 inch Louvers, Front Tilt, 2 Panels L/R Hinge, Divider Rail +/-, Divider/ Split Location: 26, TAKE DOWNS!!!	1	488.00	488.00
3	Master	Roller Shades	VU Window Treatments Master, Outside Mount, 101 inch, 100 1/2 inch, Moderna Blackout, Colour: Greige, Black Out, 4 inch Flat Fascia, White, Tear Drop White, Motor Right, TOP 2.5nM motor RF & Bluetooth USB-C, TOP 15-channel remote RF, TOP Wall Plug + Charger cable USB-C 4m, Top 6inch Usb extension, NEED SPACER BLOCK FOR TRIM	1	604.00	604.00
4	Office		VU Window Treatments Labor / Trip Fee, Office	1	125.00	125.00

--	--	--	--	--	--

### Customer Message

\*\*\*This is a custom order in which a 50% deposit is required to begin production. The final payment will be due at installation. If the installation is not completed due to a service or missing product, you will be required to pay half of the balance, and the final amount on completion.

\*\*\*Customer to remove old window treatments or other obstacles prior to installation. Any previous arrangements must be noted on this order. All free hanging verticals do not close tight. A view into the room is possible on an angle. 2" Horizontal blinds do not close tight. Light gaping will occur. This is the nature of the blind. Room darkening shades are not blackout shades unless side channels are added. With side channels there is still a possibility of light leakage.

\*\*\*No specific time of day can be promised for delivery. It is the policy of VU Window Treatments to deliver all items as quickly as possible. Unfortunately we are dependent upon our suppliers to help us meet anticipated delivery dates. Our promise of delivery is based upon deliveries to us, therefore subject to revision due to the above factors.

THIS IS A CUSTOM ORDER AND IS NOT SUBJECT TO CANCELLATION. Changes must be made within 3 days of deposit.

**\$0.00**

**Subtotal:** **\$ 2,104.00**

**Sales Tax:** **\$ 0.00**

**Total:** **\$ 2,104.00**

**Payments:** **\$ 1,050.00**

**Balance Due:** **\$ 1,054.00**

**Payment Type:** **Deposit-Check**

Installed by: \_\_\_\_\_ Date: \_\_\_\_\_

### Remittance Advice

Customer: Mr. Bob Yerger

Job Number: VU501790

Order Date: 07-18-2024

Total Due: \$ 1,054.00

Paid: \$

**Please detach and send with payment to:**

VU Window Treatments  
301a Enterprise St  
Ocoee, Florida, 34761