



301a Enterprise St  
Ocoee, Florida, 34761

Tel: 407-295-5200 Orlando  
321-622-8909 Melbourne

Website: www.VUWindowTreatments.com

## Quotation

Quotation No.
VU600689
Account Number
MONT1004
Date
11-24-2024
Sales Person
Ahren

Quote To	Mr.Tony Montoya 6032 Edgerton Ave Orlando Florida 32833E Ph: 3212026931
----------	---

Deliver To	Mr.Tony Montoya 6032 Edgerton Ave Orlando Florida 32833E Ph: 3212026931
------------	---

#	Location	Product	Description	Qty	Net	Total
1	Back North	Roller Shades	Artisan Exterior, Mount: Inside Mount, Fabric: ESSENTIAL SCREEN 1%, Fascia Type: Sealed Head Box, Fascia Color: Bronze, Bottom Rail Type and Color: Exposed Bar, Controls: Motor Left, Motorization: Artisan, Artisan Motor Option: ARTISAN 20 NM_INCLUDED, Accessories: Artisan 06 Channels, Room: Back North	1	2651.50	2,651.50
2	Back East	Roller Shades	Artisan Exterior, Mount: Inside Mount, Fabric: ESSENTIAL SCREEN 1%, Fascia Type: Sealed Head Box, Fascia Color: Bronze, Bottom Rail Type and Color: Exposed Bar, Controls: Motor Left, Motorization: Artisan, Artisan Motor Option: ARTISAN 20 NM_INCLUDED, Room: Back East	1	3295.20	3,295.20
3	south	Roller Shades	Artisan Exterior, Mount: Inside Mount, Fabric: ESSENTIAL SCREEN 1%, Fascia Type: Sealed Head Box, Fascia Color: Bronze, Bottom Rail Type and Color: Exposed Bar, Controls: Motor Left, Motorization: Artisan, Artisan Motor Option: ARTISAN 20 NM_INCLUDED, Room: south	1	2887.20	2,887.20
4		Labor/Comments	Supplier: VU Window Treatments, Charges and Comments: ZIP SHADE Trip/Labor	3	400.00	1,200.00

### Customer Message

\*\*\*This is a custom order in which a 50% deposit is required to begin production. The final payment will be due at installation. If the installation is not completed due to a service or missing product, you will be required to pay half of the balance, and the final amount on completion. \*\*\*Customer to remove old window treatments or other obstacles prior to installation. Any previous arrangements must be noted on this order. All free hanging verticals do not close tight. A view into the room is possible on an angle. 2" Horizontal blinds do not close tight. Light gaping will occur. This is the nature of the blind. Room darkening shades are not blackout shades unless side channels are added. With side channels there is still a possibility of light leakage. \*\*\*No specific time of day can be promised for delivery. It is the policy of VU Window Treatments to deliver all items as quickly as possible. Unfortunately we are dependent upon our suppliers to help us meet anticipated delivery dates. Our promise of delivery is based upon deliveries to us, therefore subject to revision due to the above factors. THIS IS A CUSTOM ORDER AND IS NOT SUBJECT TO CANCELLATION. Changes must be made within 3 days of deposit.

**Discount :** \$ 1,003.39  
**Subtotal :** \$ 9,030.51  
**Sales Tax :** \$ 0.00  
**Total :** \$ 9,030.51  
**Deposit :** \$ 0.00  
**Balance :** \$ 9,030.51

### Remittance Advice

Customer: Mr.Tony Montoya  
 Quotation No: VU600689  
 Quotation Date: 11-24-2024  
 Total Due: \$ 9,030.51  
 Paid: \$

### Please detach and send with payment to:

VU Window Treatments  
 301a Enterprise St  
 Ocoee, Florida, 34761