



QUOTATION

Quote No. 38477-a rev.2

Factory:

Cinco de Mayo, # 230-A
Col. Crosthwaite, C.P.22710
Playas de Rosarito, B.C., México.
Mex. Phone: +52 (661) 612-6988
USA Phone: 1 (702) 842-4045

Billing Information

Baja Contract, INC.
9927 Via de la Amistad
San Diego, CA 92154-7208
Contact: Yuki Peralta
Phone: (619) 601-7009

US Receiving and Shipping Warehouse

Ruffo de Alba Forwarders, LP
9927 Via de la Amistad Business Park
San Diego, CA 92154
Contact: Ricardo Montes
Phone: (619) 591-9391

TO: SKY-FRAME INC.
Contact: Ramses Calderon

Project Name: SKY-FRAME INC. - SHOW ROOM
Project Location: 1445 N. La Brea Ave. Suite C, Los Angeles, CA 90036

Today's Date: 17-Dec-24
Quote valid until: 31-Jan-25

Item	Qty	UOM	Description	I.D. Window and/or Area	Finished Width	Finished Length	Price EA	Total	
1	1	PR	RIPPLEFOLD BO LINED & UNLINED DRAPERY (CORD OPERATED)	BO LINED	SHOW ROOM - MAIN	384.000	137.000	\$ 2,216.00	\$ 2,216.00
	1	PNL	SIZES: SEE COLUMNS FOR SIZES	UNLINED	SHOW ROOM - A	127.000	159.000	\$ 675.50	\$ 675.50
	1	PNL	STYLE: RIPPLEFOLD @ 200 % FULLNESS. 2 INCHES HEAD SIZE.	UNLINED	SHOW ROOM - B	148.000	174.000	\$ 807.50	\$ 807.50
			HEMS: DOUBLE TURNED LOCKSTITCHED HEMS. 4 INCHES BOTTOM HEMS, 1.5 INCHES SIDE HEMS. WITH LEAD WEIGHTS AT CORNERS & SEAMS.						
			MOUNT: WALL MOUNT AND CEILING MOUNT.						
			HARDWARE: SEE ITEM No.3						
			CONTROL: SEE ITEM No.3						
			FABRIC: PROVIDED BY B.W.S. / / (A).-FAB-00634 / MIST or (B).-FAB-00105 / AVI / 54 GOODS						
			LINING: PROVIDED BY B.W.S. / / 3-PASS BO, WW, 110" (ONLY FOR 'SHOW ROOM - MAIN).						
						Total Item 1=		\$ 3,699.00	
2	1	EA.	CORD OPERATED ASSEMBLED TRACKS FOR RIPPLEFOLD UNLINED DRAPERIES	suspended mounting	SHOW ROOM - MAIN	384.000		\$ 1,890.00	\$ 1,890.00
	1	EA.	MOUNT: WALL MOUNT AND SUSPENDE MOUNTING FROM CEILING	ceiling mount	SHOW ROOM - A	127.000		\$ 232.40	\$ 232.40
	1	EA.	HARDWARE: EXTRUDED ALUMINUM ARCHITECTURAL ASSEMBLED UNI TRACK, POWDER COATED WHITE	ceiling mount	SHOW ROOM - B	148.000		\$ 270.80	\$ 270.80
			CONTROL: CORD OPERATED						
			NOTE: Drapery for 'show room main' must hang 3'-4" separate from wall so, a total of 11 extended 48" ceiling mount brackets will be required to support the suspended cord operated track and in addition 2 custom "L" brackets will be required to attach both ends of track to side walls.						
						Total Item 2 =		\$ 2,393.20	
3	1	EA.	1 TRIP AND TAKING OF MEASURES TO 3 WINDOWS.				\$ 670.00	\$ 670.00	
4	1	EA.	INSTALLATION OF 3 RIPPLEFOLD UNLINED DRAPERIES + CORD OPERATED HARDWARE. (dressing and/or steaming of draperies included).				\$ 1,440.00	\$ 1,440.00	

PRICES ARE FOB SAN DIEGO, CA. PACKAGING INCLUDED. FREIGHT NOT INCLUDED. DUTIES ARE INCLUDED.

LEAD TIME 3-4 WEEKS AFTER RECEIVING P.O., PREPAYMENT AND FABRICS.

PAYMENTS TERMS: 60% PREPAYMENT + 40% BALANCE ONCE INSTALLED.

LATE FEES: 5% MONTHLY INTEREST FOR 30-60 DAYS, 8% MONTHLY INTEREST FOR 60-90 DAYS AND 12% MONTHLY INTEREST FOR 90-120 DAYS

Measurement Charges are based on 1 person taking measures during 1/2 day if Rooms and/or areas are accessible all time. Downtime fee is \$250.00 per day.

Prices based on full a full availability of rooms based on 2 persons installing during 1 day., down time fee is \$250 dls. per day per installer. Additional Trip for Installation \$250.00 per Installer.

LODGING NOT INCLUDED or to be reimbursed.

COM FABRICS:

BC will not be responsible or liable for any shrinkage, discoloration, defects or other issues associated with or relating to the use of Customer's Own Materials and will only warrant workmanship as it does not apply to COM.

Fabrics swatches must be submitted with purchase order identifying the corresponding product, face and direction pattern is to be applied to product. BWS will not begin production until swatches and information has been received. Yardages are estimated based upon sizes and specifications provided. BWS will not be responsible for any additional fabrics/trims required.

Excess COM will be shipped to the property upon completion of the project unless otherwise specified in writing.

Silk Fabrics / Taffetas and Other Specialty Fabrics : When sewing silk fabrics and taffetas, there is a tendency for creasing/puckering which is inherent to the fabric and cannot be avoided or removed by methods such as steaming.

Quoted by: Julián Higuera

GRAND TOTAL= \$ 8,202.20