



# QUOTATION

Quote No. 39050rev.

**Baja Window Shading S. de R.L. de C.V.**  
 Calle Camino Vecinal, # 5051  
 Col. Benito Juarez, C.P.22706  
 Playas de Rosarito, B.C., México.  
 Mex. Phone: +52 (664) 406-4229  
 USA Phone: 1 (619) 576-6826

Project Name: ARLO WYNWOOD MUSIC VENUE  
 Project Location: MIAMI, FL

**Billing Information**  
 Di Calabria Industries Inc.  
 9927 Via de la Amistad  
 San Diego, CA 92154  
 Contact: Yukiu Peralta  
 Phone: (619) 941-2700

**US Receiving and Shipping Warehouse**  
 Ruffo de Alba Forwarders, LP  
 9927 Via de la Amistad Business Park  
 San Diego, CA 92154  
 Contact: Pamela Vera  
 Phone: (619) 591-9391

TO: JUSTIN DAVID TEXTILES  
 Contact: WENDY DESCHENE

Today's Date: 15-Jul-25  
 Quote valid until: 13-Sep-25

Item	Qty	UOM	Description	Face Yds. Req. Each	I.D. Window and/or Area	Rod Size	Finished Length	Price EA	Total
1	1	PR	<b>PINCH PLEATED STATIONARY BO UNLINED DRAPERY</b>	6.60	CUR-01	36.000	93.500	\$ 44.90	\$ 44.90
	5	PR	SIZES: SEE COLUMNS FOR SIZES	13.20	CUR-01	72.000	93.500	\$ 81.50	\$ 407.50
			STYLE: PINCH PLEATED @ 200 % FULLNESS. 4 INCHES HEAD SIZE.						
			HEMS: DOUBLE TURNED LOCKSTITCHED HEMS. 4 INCHES BOTTOM HEMS, 1.5 INCHES SIDE HEMS. WITH LEAD WEIGHTS AT CORNERS & SEAMS.						
			MOUNT: CEILING MOUNT						
			HARDWARE: SEE ITEM No.3						
			CONTROL: SEE ITEM No.3						
			FABRIC: C.O.M. / ARCHITEX / CLIPPER VILVEY / ATLANTIC / 55 GOODS		COM TOTAL FABRIC YDS. REQ. = 73				
									<b>Total Item 1= \$ 452.40</b>
2	1	EA.	<b>ASSEMBLED TRACKS FOR RIPPLEFOLD AND SHEER DRAPERIES</b>			CUR-01	36.000	\$ 17.00	\$ 17.00
	5	EA.	MOUNT: CEILING MOUNT			CUR-01	72.000	\$ 33.00	\$ 165.00
			HARDWARE: EXTRUDED ALUMINUM ARCHITECTURAL ASSEMBLED UNI TRACK, POWDER COATED WHITE						
			CONTROL: N/A TO BE STATIONARY						
									<b>Total Item 2= \$ 182.00</b>
3	1	EA.	<b>1 TRIP AND TAKING OF MEASURES TO 6 WINDOWS.</b>					\$ 1,890.00	\$ 1,890.00
4	1	EA.	<b>1 TRIP AND INSTALLATION OF 6 SETS OF SHEER DRAPERIES WITH MOTORIZED HARDWARE.</b>					\$ 2,300.00	\$ 2,300.00
5	1	EA.	<b>10% DUTIES FOR IMPORTATION OF C.O.M. FABRICS, BASED ON ESTIMATED COST (COULD VARY DEPENDING ON DECLARED COST)</b>	\$ 4.50	<b>213.00</b>			\$ 96.00	<b>DUTIES AMOUNT</b>
6	1	EA.	<b>25% DUTIES FOR EXPORTATION OVER ALUM. AND STEEL MATERIALS</b>			DUTIES %			<b>DUTIES AMOUNT</b>
7	1	EA.	<b>25% DUTIES FOR USA IMPORTATION OF FINISHED GOODS ON NON-USCMA ITEMS (PER PRESIDENT'S TRUMP FENTANYL TARIFF)</b>			0.25		\$ 23.00	<b>DUTIES AMOUNT</b>
								297.00	\$ 297.00
									<b>GRAND TOTAL= \$ 5,240.40</b>

PRICES ARE FOB SAN DIEGO CA., FREIGHT NOT INCLUDED. PACKAGING INCLUDED. DUTIES FOR EXPORTATION OF FINISHED GOODS ARE INCLUDED (ADDITIONAL DUTY CAN BE ADDED IF PRESIDENT TRUMP ANNOUNCES AS A DECRET, TO BE PAID SEPARATELY, at the time of the exportation).

LEAD TIME 4-6 WEEKS AFTER RECEIVING P.O., PREPAYMENT, C.O.M. FABRICS, AND RECAP APPROVAL

PAYMENTS TERMS: 40% PREPAYMENT + 60% BALANCE NET 15 DAYS.

**COM FABRIC IMPORTATION DUTIES AMOUNT MUST BE PAID AT THE MOMENT OF THE FABRIC IMPORTATION.**

LATE FEES: 5% MONTHLY INTEREST FOR 30-60 DAYS, 8% MONTHLY INTEREST FOR 60-90 DAYS AND 12% MONTHLY INTEREST FOR 90-120 DAYS

COM FABRICS STORAGE: BWS will storage the C.O.M. fabric without any cost during 8 weeks (2 months); starting the week number 9 of storage, BWS will charge a fee.

COM FABRICS: BWS will not be responsible or liable for any shrinkage, discoloration, defects or other issues associated with or relating to the use of Customer's Own Materials and will only warrant workmanship as it does not apply to COM. Fabrics swatches must be submitted with purchase order identifying the corresponding product, face and direction pattern is to be applied to product. BWS will not begin production until swatches and information has been received. Yardages are estimated based upon sizes and specifications provided. BWS will not be responsible for any additional fabrics/trims required.

Excess COM will be shipped to the property with the order upon completion of the project unless otherwise specified in writing.

Silk Fabrics / Taffetas / Mesh fabrics and Other Specialty Fabrics: When sewing silk fabrics and taffetas, there is a tendency for creasing/puckering which is inherent to the fabric and cannot be avoided or removed by methods such as steaming.

Mesh fabrics type are unstable as it tends to stretch and shrink; finished length of drapes using mesh fabrics can vary considerably.

Quoted by: Abel Salazar