



**US Receiving and Shipping Warehouse**  
Ruffo de Alba Forwarders, LP  
9927 Via de la Amistad Business Park  
San Diego, CA 92154  
Contact: Pamela Vera  
Phone: (619) 591-9391

TO: JUSTIN DAVID TEXTILES  
Contact: WENDY DESCHENE

Project Name: SHERATON ALBUQUERQUE  
Project Location: Albuquerque, NM.

Page 1 of 2

**Baja Window Shading S. de R.L. de C.V.**

Calle Camino Vecinal, # 5051  
Col. Benito Juarez, C.P.22706  
Playas de Rosarito, B.C., México.  
Mex. Phone: +52 (664) 406-4229  
USA Phone: 1 (619) 576-6826

**Billing Information**

Di Calabria Industries Inc.  
9927 Via de la Amistad  
San Diego, CA 92154  
Contact: Yukiu Peralta  
Phone: (619) 941-2700

**US Receiving and Shipping Warehouse**

Ruffo de Alba Forwarders, LP  
9927 Via de la Amistad Business Park  
San Diego, CA 92154  
Contact: Pamela Vera  
Phone: (619) 591-9391

# QUOTATION

**Quote No. 39417 - I rev.**

TO: JUSTIN DAVID TEXTILES  
Contact: WENDY DESCHENE

Today's Date: 03-Dec-25  
Quote valid until: 01-Feb-26

Project Name: SHERATON ALBUQUERQUE  
Project Location: Albuquerque, NM.

Item	Qty	UOM	Description	Face Yds. Req. Each	I.D. Window and/or Area	Rod Size	Finished Length	Price EA	Total
7	1	EA.	1 TRIP AND MEASUREMENT SERVICE TO MEASURE MODEL ROOM No. 637 (INCLUDES ADDTL \$100.00 TO DO THE MEASURING SERVICE ON 12/04)					\$ 1,650.00	\$ 1,650.00
8	1	EA.	1 TRIP AND INSTALLATION SERVICE FOR MODEL ROOM WITH 1 SET OF BLACKOUT AND SHEER RIPPLEFOLD DRAPERIES WITH BATON OPERATED HARDWARE					\$ 2,000.00	\$ 2,000.00

PRICES ARE FOB SAN DIEGO, PACKAGING INCLUDED. DUTIES INCLUDED + NEW TARIFFS INDICATED ON LINE ITEMS No.8, 9 & 10.

LEAD TIME 7-10 WEEKS AFTER RECEIVING P.O., PREPAYMENT, C.O.M. FABRICS AND RECAP APPROVAL.

**PAYMENTS TERMS:** 50% PREPAYMENT + 50% BALANCE NET 15 DAYS.

**LATE FEES:** 5% MONTHLY INTEREST FOR 30-60 DAYS, 8% MONTHLY INTEREST FOR 60-90 DAYS AND 12% MONTHLY INTEREST FOR 90-120 DAYS

**Effective June 4, 2025, the U.S. President Donald Trump has decreed an additional 25% tariff on imports of aluminum and steel materials so now, the tariff is 50%.  
The 25% import tax on aluminum and steel materials will remain at 25% as long as the export of the tracks takes place in kits at the same time as the draperies.  
Shipments of tracks done separately will be subject to the new 50% tax instead of the 25%.**

Measurement Charges are based on take measures during 2-2.5 working days if Rooms and/or areas are accessible all time.

Downtime fee per Measure Technician is \$250.00 per day.

Prices are based on full a full availability of rooms based on 2 persons installing during 16-17 working days.

Down time fee is \$250 dills. per day per installer. Additional Trip for Installation \$ 950 per Installer.

**LODGING NOT INCLUDED, TO BE PROVIDED BY PROPERTY , OR TO BE REIMBURSED.**

ADD \$70 cents per Linear Foot for Installation on Concrete.

**IF SCISSOR LIFT OR SCAFFOLDING ARE REQUIRED IT NEEDS TO BE PROVIDED BY GENERAL CONTRACTOR OR PROPERTY.**

**COM FABRICS STORAGE:** BWs will storage the C.O.M. fabric without any cost during 8 weeks (2 months); starting the week number 9 of storage, BWS will charge a fee of \$2.00 per roll per month..

Maximum time for fabric storage is 1 year ( fabric are imported into Mexico in a temporary manner). After 1 year, left over fabrics must be returned to USA or disposed.

**COM FABRICS:** BWS will not be responsible or liable for any shrinkage, discoloration, defects or other issues associated with or relating to the use of Customer's Own Materials and will only warrant workmanship as it does not apply to COM.

Fabrics swatches must be submitted with purchase order identifying the corresponding product, face and direction pattern is to be applied to product. BWS will not begin production until swatches and information has been received. Yardages are estimated based upon sizes and specifications provided. BWS will not be responsible for any additional fabrics/trims required.

Excess COM will be shipped to the property with the order upon completion of the project unless otherwise specified in writing.

**Silk Fabrics / Taffetas and Other Specialty Fabrics :** When sewing silk fabrics and taffetas, there is a tendency for creasing/puckering which is inherent to the fabric and cannot be avoided or removed by methods such as steaming.

**Quoted by:** Abel Salazar

**GRAND TOTAL= \$ 3,870.20**  
USD