



QUOTATION

Baja Window Shading S. de R.L. de C.V.
Calle Camino Vecinal, # 5051
Col. Benito Juarez, C.P.22706
Playas de Rosarito, B.C., México.
Mex. Phone: +52 (664) 406-4229
USA Phone: 1 (619) 576-6826

Billing Information
Di Calabria Industries Inc.
9927 Via de la Amistad
San Diego, CA 92154
Contact: Yukiu Peralta
Phone: (619) 941-2700

US Receiving and Shipping Warehouse
Ruffo de Alba Forwarders, LP
9927 Via de la Amistad Business Park
San Diego, CA 92154
Contact: Pamela Vera
Phone: (619) 591-9391

Quote No. 39698

TO: DIAMANTÉ WORLDWIDE
Contact: Brandi Gardner

Today's Date: 14-Nov-25
Quote valid until: 13-Jan-26

Project Name: MIPTOWN HOTEL BOSTON PA APP

Project Location: _____

PRICES ARE FOB SAN DIEGO, PACKAGING INCLUDED, DUTIES INCLUDED + NEW TARIFF INDICATED ON LINE ITEMS No. 6 & 7.

GRAND TOTAL = \$ 390.30

LEAD TIME 4-6 WEEKS AFTER RECEIVING P.O. PREPAYMENT AND C.O.M. FABRICS

PAYMENTS TERMS: 50% PREPAYMENT + 50% BALANCE NET 15 DAYS

5% MONTHLY INTEREST FOR 30-60 DAYS, 8% MONTHLY INTEREST FOR 60-90 DAYS AND 12% MONTHLY INTEREST FOR 90-120 DAYS.

COM FABRICS STORAGE: BWS will storage the C.O.M. fabric without any cost during 8 weeks (2 months); starting the week number 9 of storage, BWS will charge a fee of \$2.00 per roll per month.

COM FABRICS STORAGE: BWS will store the C.O.M. fabric without any cost during 6 weeks (2 months), starting the week number 9 of storage, BWS will charge a fee of \$2.00 per full ton per month..

COM FABRICS. BWS will not be responsible or liable for any shrinkage, discoloration, defects or other issues associated with or relating to the use of Customer's own materials and will not warrant workmanship as it does not apply to fabrics swatches must be submitted with purchase order identifying the corresponding product, face and direction pattern is to be applied to product. BWS will not begin production until swatches and information

Silk Fabrics / Taffetas / Mesh fabrics and Other Specialty Fabrics : When sewing silk fabrics and taffetas, there is a tendency for creasing/puckering which is inherent to the fabric and cannot be avoided or removed by methods

Quoted by [Abel Galazan](#)