

Shelley Franklin

From: Brian Watson <brianwatson035@gmail.com>
Sent: Wednesday, January 7, 2026 5:14 PM
To: Shelley Franklin
Cc: Jonathan Marcinkowski
Subject: Spark Douglasville, GA. Fitness Shade issue & Install trip photos

EXTERNAL EMAIL

Secured by Check Point

Shelley,

Per our conversation, the fitness shade came in 1.25" too narrow for the window opening.
Per the owner we installed the brackets and his maintenance personnel will install the replacement shade made to the correct size.
The windows width opening is 70"w and the actual measurement from inside bracket to inside of adjacent bracket is 69 & 7/8.
The factory had the length correct on the shade sent.

Please see attached photos link below.

Best Regards,
Brian

<https://photos.app.goo.gl/JNoPE79qZs3uVwQ88>