



301a Enterprise St  
Ocoee, Florida, 34761

Tel/Fax: 407-295-5200 Orlando 321-622-8909 Melbourne  
Email:  
Website: www.VUWindowTreatments.com

## Quotation

Quotation No.
VU500082
Account Number
SCHL1001
Date
03-10-2023
Sales Person
Ahren

Quote To	_ Doug Schlett, 18525 Down way Rd, Clermont, FL, 34715 4073537977 dwsiphone@embarqmail.com
----------	--

Deliver To	_ Doug Schlett, 18525 Down way Rd, Clermont, FL, 34715 4073537977 dwsiphone@embarqmail.com
------------	--

#	Location	Product	Description	Qty	Net	Total
1	Porch 1	Roller Shades	Porch 1, Inside Mount, 5%Sunshade, Range 2, 4 inch Flat Fascia, Black, Tear Drop B/R Black, Motor Right, Stainless Chain, Somfy Charger for Battery Built in Motor, Somfy Emitter 5 Channels, Somfy App Control My LINK	1	1148.46	1,148.46
2	Porch 2	Roller Shades	Porch 2, Inside Mount, 5%Sunshade, Range 2, 4 inch Flat Fascia, Black, Tear Drop B/R Black, Motor Right, Stainless Chain, Somfy From 96 up to 118 Shades - 3 N - 28 RPM, Somfy Charger for Battery Built in Motor	1	1044.44	1,044.44
3	Porch 3	Roller Shades	Porch 3, Inside Mount, 5%Sunshade, Range 2, 4 inch Flat Fascia, Black, Tear Drop B/R Black, Motor Right, Stainless Chain, Somfy From 96 up to 118 Shades - 3 N - 28 RPM, Somfy Charger for Battery Built in Motor	1	1414.75	1,414.75
4	Porch 4	Roller Shades	Porch 4, Inside Mount, 5%Sunshade, Range 2, 4 inch Flat Fascia, Black, Tear Drop B/R Black, Motor Right, Stainless Chain, Somfy From 96 up to 118 Shades - 3 N - 28 RPM, Somfy Charger for Battery Built in Motor	1	1341.40	1,341.40
5	Porch 1	Labor / Trip Fee, 4 FOOT LADDER	Room:: Porch 1, : Labor / Trip Fee, 4 FOOT LADDER, Special Instructions:: 1 bracket is concrete.	1	85.00	85.00

### Customer Message

\*\*\*This is a custom order in which the order should be paid in full to begin production. A deposit is required. The final payment will be due at installation. If the installation is not completed due to a service or missing product, you may pay 40% of the balance, and the final 10% on completion.

\*\*\*Customer to remove old window treatments or other obstacles prior to installation. Any previous arrangements must be noted on this order. All free hanging verticals do not close tight. A view into the room is possible on an angle. 2" Horizontal blinds do not close tight. Light gapping will occur. This is the nature of the blind. Room darkening shades are not blackout shades unless side channels are added. With side channels there is still a possibility of light leakage.

\*\*\*No specific time of day can be promised for delivery. It is the policy of VU Window Treatments to deliver all items as quickly as possible. Unfortunately we are dependent upon our suppliers to help us meet anticipated delivery dates. Our promise of delivery is based upon deliveries to us, therefore subject to revision due to the above factors.

THIS IS A CUSTOM ORDER AND IS NOT SUBJECT TO CANCELLATION. Changes must be made within 3 days of deposit.

**\$0.00**  
**Subtotal: \$ 5,034.05**  
**Sales Tax: \$ 352.38**  
**Total: \$ 5,386.43**  
**Deposit : \$ 0.00**  
**Balance: \$ 5,386.43**

### Remittance Advice

Customer: \_ Doug Schlett  
Quotation No: VU500082  
Quotation Date: 03-10-2023  
Total Due: \$ 5,386.43  
Paid: \$

### Please detach and send with payment to:

VU Window Treatments  
301a Enterprise St  
Ocoee, Florida, 34761