



301a Enterprise St
Ocoee, Florida, 34761

Tel/Fax: 407-295-5200 Orlando 321-622-8909 Melbourne
Email:
Website: www.VUWindowTreatments.com

Quotation

Quotation No.
VU500906
Account Number
HWO Holdings LLC
Date
10-18-2023
Sales Person
Ahren

Quote To	Mrs. Pat Brown, HWO Holdings LLC, 1200 E Plant St, WG, FL, 34787 4073376919 108 pbrown@fhwo.org
-----------------	---

Deliver To	Mrs. Pat Brown, HWO Holdings LLC, 1200 E Plant St, WG, FL, 34787 4073376919 108 pbrown@fhwo.org
-------------------	---

#	Location	Product	Description	Qty	Net	Total
1	Conf w1	Roller Shades	Conf w1, Inside Mount, 4 inch Flat Fascia, Bronze, Clutch Right, Stainless Chain, VU 110V Motor Any Size AM45-15	1	365.00	365.00
2		Labor / Trip Fee	Labor / Trip Fee, uninstall 3 shades. mount new brackets + tube + fascia. Reuse fabric. 3 on 1 tube.	1	85.00	85.00
3	Conf w3	Roller Shades	Conf w3, Inside Mount, 4 inch Flat Fascia, Bronze, Clutch Right, Stainless Chain, VU 110V Motor Any Size AM45-15	1	405.41	405.41
4		Labor / Trip Fee	Labor / Trip Fee, uninstall 3 shades. mount new brackets + tube + fascia. Reuse fabric. 3 on 1 tube.	1	85.00	85.00
5	Conf w2	Roller Shades	Conf w2, Inside Mount, 4 inch Flat Fascia, Bronze, Clutch Right, Stainless Chain, VU 110V Motor Any Size AM45-15	1	405.41	405.41
6		Labor / Trip Fee	Labor / Trip Fee, uninstall 3 shades. mount new brackets + tube + fascia. Reuse fabric. 3 on 1 tube.	1	85.00	85.00
7	Conf w4	Roller Shades	Conf w4, Inside Mount, 4 inch Flat Fascia, Bronze, Clutch Right, Stainless Chain, VU 110V Motor Any Size AM45-15	1	405.41	405.41
8		Labor / Trip Fee	Labor / Trip Fee, uninstall 3 shades. mount new brackets + tube + fascia. Reuse fabric. 3 on 1 tube.	1	85.00	85.00

Customer Message

***This is a custom order in which a 50% deposit is required to begin production. The final payment will be due at installation. If the installation is not completed due to a service or missing product, you may pay half of the balance, and the final amount on completion.

***Customer to remove old window treatments or other obstacles prior to installation. Any previous arrangements must be noted on this order. All free hanging verticals do not close tight. A view into the room is possible on an angle. 2" Horizontal blinds do not close tight. Light gaping will occur. This is the nature of the blind. Room darkening shades are not blackout shades unless side channels are added. With side channels there is still a possibility of light leakage.

***No specific time of day can be promised for delivery. It is the policy of VU Window Treatments to deliver all items as quickly as possible. Unfortunately we are dependent upon our suppliers to help us meet anticipated delivery dates. Our promise of delivery is based upon deliveries to us, therefore subject to revision due to the above factors.

THIS IS A CUSTOM ORDER AND IS NOT SUBJECT TO CANCELLATION. Changes must be made within 3 days of deposit.

	\$0.00
Subtotal:	\$ 1,921.23
Sales Tax:	\$ 0.00
Total:	\$ 1,921.23
Deposit :	\$ 0.00
Balance:	\$ 1,921.23

Remittance Advice

Customer: HWO Holdings LLC
Quotation No: VU500906
Quotation Date: 10-18-2023
Total Due: \$ 1,921.23
Paid: \$

Please detach and send with payment to:

VU Window Treatments
301a Enterprise St
Ocoee, Florida, 34761