



301a Enterprise St  
Ocoee, Florida, 34761

Tel/Fax: 407-295-5200 Orlando 321-622-8909 Melbourne  
Email:  
Website: [www.VUWindowTreatments.com](http://www.VUWindowTreatments.com)

Quotation	
Quotation No.	
	VU501282
Account Number	
	EMERSON REAL ESTATE SERVICES INC
Date	
	02-28-2024
Sales Person	
	Ahren

<b>Quote To</b>	Mr. Johnny Howard, Emerson Real Estate Services, Inc., 283 Cranes Roost Blvd, Suite 250 Altamonte Springs, FL, 32701 4076211061 LSnow@emerson-us.com	<b>Deliver To</b>	5728 Major Blvd Orlando, FL, 32819
-----------------	---	-------------------	---------------------------------------

#	Location	Product	Description	Qty	Net	Total
1	Suite 720		Labor / Trip Fee, Suite 720	1	125.00	125.00
2	Open w10 broken carrier	Verticals	Open w10 broken carrier, IB, OWR, Clear Edge Square Corners, New - Track Only	1	33.00	33.00
3	Open w10 broken carrier	Slats ONLY	Open w10 broken carrier, EXACT, 60 3/4 inch, Curved, Off White JD-8018, Price Group 1	1	4.22	4.22
4	Open w13 broken carrier	Verticals	Open w13 broken carrier, IB, OWR, Clear Edge Square Corners, New - Track Only	1	24.75	24.75
5	Open w15 broken carrier	Verticals	Open w15 broken carrier, IB, OWR, Clear Edge Square Corners, New - Track Only	1	22.50	22.50
6	Open w15 broken carrier	Slats ONLY	Open w15 broken carrier, EXACT, 60 3/4 inch, Curved, Off White JD-8018, Price Group 1	1	4.22	4.22

#### Customer Message

\*\*\*This is a custom order in which a 50% deposit is required to begin production. The final payment will be due at installation. If the installation is not completed due to a service or missing product, you may pay half of the balance, and the final amount on completion.

\*\*\*Customer to remove old window treatments or other obstacles prior to installation. Any previous arrangements must be noted on this order. All free hanging verticals do not close tight. A view into the room is possible on an angle. 2" Horizontal blinds do not close tight. Light gaping will occur. This is the nature of the blind. Room darkening shades are not blackout shades unless side channels are added. With side channels there is still a possibility of light leakage.

\*\*\*No specific time of day can be promised for delivery. It is the policy of VU Window Treatments to deliver all items as quickly as possible. Unfortunately we are dependent upon our suppliers to help us meet anticipated delivery dates. Our promise of delivery is based upon deliveries to us, therefore subject to revision due to the above factors.

THIS IS A CUSTOM ORDER AND IS NOT SUBJECT TO CANCELLATION. Changes must be made within 3 days of deposit.

	\$ 0.00
<b>Subtotal:</b>	\$ 213.69
<b>Sales Tax:</b>	\$ 13.89
<b>Total:</b>	\$ 227.58
<b>Deposit :</b>	\$ 0.00
<b>Balance:</b>	\$ 227.58

#### Remittance Advice

Customer: Mr. Johnny Howard  
Quotation No: VU501282  
Quotation Date: 02-28-2024  
Total Due: \$ 227.58  
Paid: \$

Please detach and send with payment to:

VU Window Treatments  
301a Enterprise St  
Ocoee, Florida, 34761