



301a Enterprise St
Ocoee, Florida, 34761

Tel/Fax: 407-295-5200 Orlando /407-292-7691
Email: 321-622-8909 Melbourne
Website: www.VUWindowTreatments.com

Order Confirmation

Job Number
VU501523
Account Number
SCOT1005
Order Date
Sales Person
Ahren
Customer Reference

Invoice To	Mr. Daryl Scott, 1007 Johns Pointe Dr, Oakland, FL, 34787 4074607334 daryllancescott@gmail.com
------------	--

Deliver To	Mr. Daryl Scott, 1007 Johns Pointe Dr, Oakland, FL,34787 4074607334 daryllancescott@gmail.com
------------	---

#	Location	Product	Description	Qty	Net	Total
1	Bay	Roller Shades	VU Window Treatments Bay, Inside Mount, 24 1/8 inch, 83 inch, Swing, TWC 3, 3inch Cassette with Fabric Insert, Ivory, Tear Drop Ivory, Motor Left, TOP Wall Plug + Charger cable USB-C 4m, Top 6inch Usb extension, TOP 1.1nM motor RF & Bluetooth USB-C, TOP 5-channel remote RF, color	1	426.55	426.55
2	Bay 2	Roller Shades	VU Window Treatments Bay 2, Inside Mount, 58 5/8 inch, 83 inch, Swing, TWC 3, 3inch Cassette with Fabric Insert, Ivory, Tear Drop Ivory, Motor Left, TOP Wall Plug + Charger cable USB-C 4m, Top 6inch Usb extension, TOP 1.1nM motor RF & Bluetooth USB-C, color dune	1	512.02	512.02
3	Bay 3	Roller Shades	VU Window Treatments Bay 3, Inside Mount, 24 1/2 inch, 83 inch, Swing, TWC 3, 3inch Cassette with Fabric Insert, Ivory, Tear Drop Ivory, Motor Left, TOP Wall Plug + Charger cable USB-C 4m, Top 6inch Usb extension, TOP 1.1nM motor RF & Bluetooth USB-C, color dune	1	392.97	392.97
4	Bay		VU Window Treatments Labor / Trip Fee, Bay	1	125.00	125.00
5	Bay		VU Window Treatments Buy 2 get 1 Free, Bay	393	-1.00	-393.00

--	--	--	--	--	--	--

Customer Message

***This is a custom order in which a 50% deposit is required to begin production. The final payment will be due at installation. If the installation is not completed due to a service or missing product, you may pay half of the balance, and the final amount on completion.

***Customer to remove old window treatments or other obstacles prior to installation. Any previous arrangements must be noted on this order. All free hanging verticals do not close tight. A view into the room is possible on an angle. 2" Horizontal blinds do not close tight. Light gaping will occur. This is the nature of the blind. Room darkening shades are not blackout shades unless side channels are added. With side channels there is still a possibility of light leakage.

***No specific time of day can be promised for delivery. It is the policy of VU Window Treatments to deliver all items as quickly as possible. Unfortunately we are dependent upon our suppliers to help us meet anticipated delivery dates. Our promise of delivery is based upon deliveries to us, therefore subject to revision due to the above factors.

THIS IS A CUSTOM ORDER AND IS NOT SUBJECT TO CANCELLATION. Changes must be made within 3 days of deposit.

	\$0.00
Subtotal:	\$ 1,063.54
Sales Tax:	\$ 69.14
Total:	\$ 1,132.68
Payments:	\$ 710.00
Balance Due:	\$ 422.68
Payment Type:	Deposit-Check

Installed by: _____ Date: _____

Remittance Advice

Customer:
Job Number: VU501523
Order Date: 05-02-2024
Total Due: \$ 422.68
Paid: \$

Please detach and send with payment to:

VU Window Treatments
301a Enterprise St
Ocoee, Florida, 34761



Signed by Daryl Scott