



301a Enterprise St  
Ocoee, Florida, 34761

Tel/Fax: 407-295-5200 Orlando / 407-292-7691  
Email: 321-622-8909 Melbourne  
Website: www.VUWindowTreatments.com

### Quotation

Quotation No.
VU501736
Account Number
JIME1002
Date
07-02-2024
Sales Person
Ahren

<b>Quote To</b>	Mr. Ruben Jimenez, 556 Autumn Ash Dr, Clermont, FL, 34715 9544781142 rj352@centurylink.net	<b>Deliver To</b>	Mr. Ruben Jimenez, 556 Autumn Ash Dr, Clermont, FL, 34715 9544781142 rj352@centurylink.net
-----------------	--	-------------------	--

#	Location	Product	Description	Qty	Net	Total
1	Porch w1	Roller Shades	Porch w1, Outside Mount, 3% Sunshade, Black + Black 2001, Sunshade, 4 inch Flat Fascia, Black, Tear Drop Black, Motor Right, TOP 1.5nM motor RF & Bluetooth USB-C, TOP 15-channel remote RF, TOP Wall Plug + Charger cable USB-C 4m, Exterior Draper Cable Guides C501.374, INSTALL ON METAL	1	700.42	700.42
2	Porch w2	Roller Shades	Porch w2, Outside Mount, 3% Sunshade, Black + Black 2001, Sunshade, 4 inch Flat Fascia, Black, Tear Drop Black, Motor Right, TOP 1.5nM motor RF & Bluetooth USB-C, TOP Wall Plug + Charger cable USB-C 4m, Exterior Draper Cable Guides C501.374, INSTALL ON METAL	1	650.42	650.42
3	Porch w3	Roller Shades	Porch w3, Outside Mount, 3% Sunshade, Black + Black 2001, Sunshade, 4 inch Flat Fascia, Black, Tear Drop Black, Motor Right, TOP 1.5nM motor RF & Bluetooth USB-C, TOP Wall Plug + Charger cable USB-C 4m, Exterior Draper Cable Guides C501.374, INSTALL On Concrete. MOVE SHADE OUT TO MISS DOOR CLOSER	1	509.40	509.40
4	Porch w1		Labor / Trip Fee, Porch w1	1	125.00	125.00

### Customer Message

\*\*\*This is a custom order in which a 50% deposit is required to begin production. The final payment will be due at installation. If the installation is not completed due to a service or missing product, you may pay half of the balance, and the final amount on completion.

\*\*\*Customer to remove old window treatments or other obstacles prior to installation. Any previous arrangements must be noted on this order. All free hanging verticals do not close tight. A view into the room is possible on an angle. 2" Horizontal blinds do not close tight. Light gaping will occur. This is the nature of the blind. Room darkening shades are not blackout shades unless side channels are added. With side channels there is still a possibility of light leakage.

\*\*\*No specific time of day can be promised for delivery. It is the policy of VU Window Treatments to deliver all items as quickly as possible. Unfortunately we are dependent upon our suppliers to help us meet anticipated delivery dates. Our promise of delivery is based upon deliveries to us, therefore subject to revision due to the above factors.

THIS IS A CUSTOM ORDER AND IS NOT SUBJECT TO CANCELLATION. Changes must be made within 3 days of deposit.

Discount: \$198.52  
Subtotal: \$ 1,786.72  
Sales Tax: \$ 116.14  
Total: \$ 1,902.85

Deposit : \$ 0.00  
Balance: \$ 1,902.85

### Remittance Advice

Customer: Mr. Ruben Jimenez  
Quotation No: VU501736  
Quotation Date: 07-02-2024  
Total Due: \$ 1,902.85  
Paid: \$

Please detach and send with payment to:

VU Window Treatments  
301a Enterprise St  
Ocoee, Florida, 34761