



301a Enterprise St
Ocoee, Florida, 34761

Tel/Fax: 407-295-5200 Orlando /407-292-7691
Email: 321-622-8909 Melbourne
Website: www.VUWindowTreatments.com

Quotation

Quotation No.
VU501741
Account Number
Orlando Health Winnie Palmer Hospital
Date
07-02-2024
Sales Person
Ahren

Quote To	Mr. Daniel Miranda, Orlando Health Winnie Palmer Hospital, 83 W Miller Ave, Orlando, FL, 32806E 4074270714 daniel.miranda@orlandohealth.com
----------	--

Deliver To	3rd Floor POD 3 ,
------------	----------------------

#	Location	Product	Description	Qty	Net	Total
1	356	Roller Shades	356, Inside Mount, Motor Right	1		
2	354	Roller Shades	354, Inside Mount, Motor Left	1		
3	354	Roller Shades	354, Inside Mount, Motor Left	1		
4	352	Roller Shades	352, Inside Mount, Motor Right	1		
5	352	Roller Shades	352, Inside Mount, Motor Right	1		
6	350	Roller Shades	350, Inside Mount, Motor Left	1		
7	350	Roller Shades	350, Inside Mount, Motor Left	1		
8	348	Roller Shades	348, Inside Mount, Motor Right	1		
9	348	Roller Shades	348, Inside Mount, Motor Right	1		
10	346	Roller Shades	346, Inside Mount, Motor Left	1		
11	346	Roller Shades	346, Inside Mount, Motor Left	1		
12			Shipping	1		
13		Roller Shades	Sealed, Dual Zone Wall Switch	7		
14			9- 1foot cat 5 cables 8- 10foot cat 5 9-20 foot cat 5	1		
15	3rd Floor NIC unit POD3		Labor / Trip Fee (Discounted), 3rd Floor NIC unit POD3	1		

--	--	--	--	--	--	--

Customer Message

***This is a custom order in which a 50% deposit is required to begin production. The final payment will be due at installation. If the installation is not completed due to a service or missing product, you will be required to pay half of the balance, and the final amount on completion.

***Customer to remove old window treatments or other obstacles prior to installation. Any previous arrangements must be noted on this order. All free hanging verticals do not close tight. A view into the room is possible on an angle. 2" Horizontal blinds do not close tight. Light gaping will occur. This is the nature of the blind. Room darkening shades are not blackout shades unless side channels are added. With side channels there is still a possibility of light leakage.

***No specific time of day can be promised for delivery. It is the policy of VU Window Treatments to deliver all items as quickly as possible. Unfortunately we are dependent upon our suppliers to help us meet anticipated delivery dates. Our promise of delivery is based upon deliveries to us, therefore subject to revision due to the above factors.

THIS IS A CUSTOM ORDER AND IS NOT SUBJECT TO CANCELLATION. Changes must be made within 3 days of deposit.

	\$0.00
Subtotal:	\$ 18,990.80
Sales Tax:	\$ 0.00
Total:	\$ 18,990.80
Deposit :	\$ 0.00
Balance:	\$ 18,990.80

Remittance Advice

Customer:	Mr. Daniel Miranda
Quotation No:	VU501741
Quotation Date:	07-02-2024
Total Due:	\$ 18,990.80
Paid:	\$

Please detach and send with payment to:

VU Window Treatments
301a Enterprise St
Ocoee, Florida, 34761