



301a Enterprise St
Ocoee, Florida, 34761

Tel/Fax: 407-295-5200 Orlando /407-292-7691
Email: 321-622-8909 Melbourne
Website: www.VUWindowTreatments.com

Order Confirmation

Job Number
VU501886
Account Number
CARR1007
Order Date
09-20-2024
Sales Person
Ahren
Customer Reference
Noemi Carrasquillo

Invoice To	Mrs. Milly Carrasquillo, 5401 Leighton Ln, Oviedo, FL, 32765E 4075918880 millzcarrasquillo@gmail.com
------------	--

Deliver To	Mrs. Milly Carrasquillo, 5401 Leighton Ln, Oviedo, FL,32765E 4075918880 millzcarrasquillo@gmail.com
------------	---

#	Location	Product	Description	Qty	Total
1	Liv w1	Smart Shutter	VU Window Treatments Liv w1, Frame: Trim, 3 with Add Sill Plate, Inside, 24 7/8 inch, 69 1/2 inch, White, 4 inch Louvers, Back Tilt, 1 Panel Left Hinge, Divider Rail +/-, Divider/Split Location: 31, TAKE DOWNS!!!	1	405.98
2	Liv w2	Smart Shutter	VU Window Treatments Liv w2, Frame: Trim, 3 with Add Sill Plate, Inside, 24 3/4 inch, 69 1/2 inch, White, 4 inch Louvers, Back Tilt, 1 Panel Right Hinge, Divider Rail +/-, Divider/Split Location: 31, TAKE DOWNS!!!	1	405.98
3	Liv w3	Smart Shutter	VU Window Treatments Liv w3, Frame: Trim, 3 with Add Sill Plate, Inside, 35 1/4 inch, 69 1/2 inch, White, 4 inch Louvers, Back Tilt, 1 Panel Left Hinge, Divider Rail +/-, Divider/Split Location: 31, TAKE DOWNS!!!	1	558.38
4	Liv w4	Smart Shutter	VU Window Treatments Liv w4, Frame: Trim, 3 with Add Sill Plate, Inside, 35 3/8 inch, 69 1/2 inch, White, 4 inch Louvers, Back Tilt, 1 Panel Right Hinge, Divider Rail +/-, Divider/Split Location: 31, TAKE DOWNS!!!	1	558.38
5	Slider	Smart Shutter	VU Window Treatments Slider, Frame: Bypass Frame, 3 Sides with Valance, Inside, 71 1/2 inch, 93 7/8 inch, White, 4 inch Louvers, Back Tilt, Bipass 2 Panels, Divider Rail +/-, Divider/Split Location: 74	1	1,356.00
6	Up bed 1	Smart Shutter	VU Window Treatments Up bed 1, Frame: Trim, 3 with Add Sill Plate, Inside, 35 1/4 inch, 59 inch, White, 4 inch Louvers, Back Tilt, 1 Panel Right Hinge, Divider Rail +/-, Divider/Split Location: 31, TAKE DOWNS!!!	1	476.04
7	Up bed 2	Smart Shutter	VU Window Treatments Up bed 2, Frame: Trim, 3 with Add Sill Plate, Inside, 35 3/8 inch, 59 inch, White, 4 inch Louvers, Back Tilt, 1 Panel Left Hinge, Divider Rail +/-, Divider/Split Location: 31, TAKE DOWNS!!!	1	476.04
8	Up bed 2 Right	Smart Shutter	VU Window Treatments Up bed 2 Right, Frame: Trim, 3 with Add Sill Plate, Inside, 35 1/2 inch, 59 inch, White, 4 inch Louvers, Back Tilt, 1 Panel Right Hinge, Divider Rail +/-, Divider/Split Location: 31, TAKE DOWNS!!!	1	476.04
9	Master	Smart Shutter	VU Window Treatments Master, Frame: Trim, 3 with Add Sill Plate, Inside, 35 1/2 inch, 59 inch, White, 4 inch Louvers, Back Tilt, 1 Panel Left Hinge, Divider Rail +/-, Divider/Split Location: 31, TAKE DOWNS!!!	1	476.04
10	Master Right	Smart Shutter	VU Window Treatments Master Right, Frame: Trim, 3 with Add Sill Plate, Inside, 35 1/2 inch, 59 inch, White, 4 inch Louvers, Back Tilt, 1 Panel Right Hinge, Divider Rail +/-, Divider/Split Location: 31, TAKE DOWNS!!!	1	476.04

#	Location	Product	Description	Qty	Total
11	Liv w1		VU Window Treatments Labor / Trip Fee, Liv w1	1	125.00
12	Entry	Smart Shutter	VU Window Treatments Entry, Frame: Trim, 4 sides, Inside, 22 3/8 inch, 21 1/2 inch, White, 4 inch Louvers, Back Tilt, 1 Panel Left Hinge	1	115.28
13	Entry	Smart Shutter	VU Window Treatments Entry, Frame: Trim, 4 sides, Inside, 22 1/4 inch, 21 1/2 inch, White, 4 inch Louvers, Back Tilt, 1 Panel Right Hinge	1	115.28
14	Liv w1		VU Window Treatments GET 30% TAX CREDIT - UP TO \$1200 on Shutter Smart -LIFETIME WARRANTY, Liv w1	1	

Customer Message

***This is a custom order in which a 50% deposit is required to begin production. The final payment will be due at installation. If the installation is not completed due to a service or missing product, you will be required to pay half of the balance, and the final amount on completion.

***Customer to remove old window treatments or other obstacles prior to installation. Any previous arrangements must be noted on this order. All free hanging verticals do not close tight. A view into the room is possible on an angle. 2" Horizontal blinds do not close tight. Light gaping will occur. This is the nature of the blind. Room darkening shades are not blackout shades unless side channels are added. With side channels there is still a possibility of light leakage.

***No specific time of day can be promised for delivery. It is the policy of VU Window Treatments to deliver all items as quickly as possible. Unfortunately we are dependent upon our suppliers to help us meet anticipated delivery dates. Our promise of delivery is based upon deliveries to us, therefore subject to revision due to the above factors.

THIS IS A CUSTOM ORDER AND IS NOT SUBJECT TO CANCELLATION. Changes must be made within 3 days of deposit.

Discount: \$ 602.05

Subtotal: \$ 5,418.43

Sales Tax: \$ 0.00

Total: \$ 5,418.43

Payments: \$ 2,709.00

Balance Due: \$ 2,709.43

Payment Type: Deposit-Visa

Installed by: _____ Date: _____

Remittance Advice

Customer: Mrs. Milly Carrasquillo

Job Number: VU501886

Order Date: 08-15-2024

Total Due: \$ 2,709.43

Paid: \$ _____

Please detach and send with payment to:

VU Window Treatments
301a Enterprise St
Ocoee, Florida, 34761