



301a Enterprise St
Ocoee, Florida, 34761

Tel/Fax: 407-295-5200 Orlando /407-292-7691
Email: 321-622-8909 Melbourne
Website: www.VUWindowTreatments.com

Order Confirmation

Job Number
VU501407R
Account Number
MELL1003
Order Date
05-15-2024
Sales Person
Ahren
Customer Reference

Invoice To	Mr. Mike Mellado, MJS Construction, 1060 Woodcock Rd, Orlando, FL, 32803 3212311113 mike@mjs247.com	Deliver To	610 Alhambra Ave Altamonte Springs, FL, 32714
-------------------	--	-------------------	--

#	Location	Product	Description	Qty	Net	Total
1	porch 1	Roller Shades	VU Window Treatments porch 1, Outside Mount, 70 1/2 inch, 102 inch, 3% Sunshade, White + Grey 2200, Sunshade, NO FASCIA, Tear Drop Grey/Alum, Grey Plastic Chain, Exterior Draper Cable Guides C501.374	1	0.00	
2	porch	Roller Shades	VU Window Treatments porch, Outside Mount, 60 1/4 inch, 102 inch, 3% Sunshade, White + Grey 2200, Sunshade, NO FASCIA, Tear Drop Grey/Alum, Grey Plastic Chain, Exterior Draper Cable Guides C501.374	1	0.00	
3	porch	Roller Shades	VU Window Treatments porch, Outside Mount, 68 inch, 102 inch, 3% Sunshade, White + Grey 2200, Sunshade, NO FASCIA, Tear Drop Bronze, Exterior Draper Cable Guides C501.374	1	0.00	
4	porch 4	Roller Shades	VU Window Treatments porch 4, Outside Mount, 71 1/4 inch, 102 inch, 3% Sunshade, White + Grey 2200, Sunshade, NO FASCIA, Tear Drop Grey/Alum, Grey Plastic Chain, Exterior Draper Cable Guides C501.374	1	0.00	
5			VU Window Treatments CUSTOMER STATES SHADE 1 AND SHADE 3 NEED TO SWITCH POSITIONS. INSTALLED WRONG. GAPS ON SIDES.	1	0.00	

--	--	--	--	--	--

Customer Message

***This is a custom order in which a 50% deposit is required to begin production. The final payment will be due at installation. If the installation is not completed due to a service or missing product, you may pay half of the balance, and the final amount on completion.

***Customer to remove old window treatments or other obstacles prior to installation. Any previous arrangements must be noted on this order. All free hanging verticals do not close tight. A view into the room is possible on an angle. 2" Horizontal blinds do not close tight. Light gaping will occur. This is the nature of the blind. Room darkening shades are not blackout shades unless side channels are added. With side channels there is still a possibility of light leakage.

***No specific time of day can be promised for delivery. It is the policy of VU Window Treatments to deliver all items as quickly as possible. Unfortunately we are dependent upon our suppliers to help us meet anticipated delivery dates. Our promise of delivery is based upon deliveries to us, therefore subject to revision due to the above factors.

THIS IS A CUSTOM ORDER AND IS NOT SUBJECT TO CANCELLATION. Changes must be made within 3 days of deposit.

Subtotal:	\$ 0.00
Sales Tax:	\$ 0.00
Total:	\$ 0.00
Payments:	\$ 0.00
Balance Due:	\$ 0.00

Payment Type:

Installed by: _____ Date: _____

Remittance Advice

Customer: Mr. Mike Mellado

Job Number: VU501407R

Order Date: 05-15-2024

Total Due: \$ 0.00

Paid: \$

Please detach and send with payment to:

VU Window Treatments
301a Enterprise St
Ocoee, Florida, 34761