



301a Enterprise St  
Ocoee, Florida, 34761

Tel/Fax: 407-295-5200 Orlando /407-292-7691  
Email: 321-622-8909 Melbourne  
Website: www.VUWindowTreatments.com

### Quotation

Quotation No.
VU501634
Account Number
MADH1001
Date
06-05-2024
Sales Person
Ahren

<b>Quote To</b>	Mrs. Mabhuir Pullela, 12185 S Apopka Vineland Rd, Orlando, FL, 32836 4075750763 Naatunaatuveg@gmail.com	<b>Deliver To</b>	Mrs. Mabhuir Pullela, 12185 S Apopka Vineland Rd, Orlando, FL, 32836 4075750763 Naatunaatuveg@gmail.com
-----------------	---	-------------------	---

#	Location	Product	Description	Qty	Net	Total
1	Front w1	Roller Shades	Front w1, Outside Mount, 3% Sunshade, Black + Black 2001, Sunshade, NO FASCIA, Tear Drop Black, Clutch Left	1	183.31	183.31
2	Front w2	Roller Shades	Front w2, Outside Mount, 3% Sunshade, Black + Black 2001, Sunshade, NO FASCIA, Tear Drop Black, Clutch Left	1	183.31	183.31
3	Front w3	Roller Shades	Front w3, Outside Mount, 3% Sunshade, Black + Black 2001, Sunshade, NO FASCIA, Tear Drop Black, Clutch Left	1	183.31	183.31
4	Front w4	Roller Shades	Front w4, Outside Mount, 3% Sunshade, Black + Black 2001, Sunshade, NO FASCIA, Tear Drop Black, Clutch Left	1	183.31	183.31
5	Front door	Roller Shades	Front door, Inside Mount, 3% Sunshade, Black + Black 2001, Sunshade, NO FASCIA, Square Black, Clutch Left, Plastic Hold Downs	1	148.02	148.02
6	Front door right	Roller Shades	Front door right, Inside Mount, 3% Sunshade, Black + Black 2001, Sunshade, NO FASCIA, Square Black, Clutch Right, Plastic Hold Downs	1	148.02	148.02
7	Front w1		Labor / Trip Fee, Front w1	1	125.00	125.00

### Customer Message

\*\*\*This is a custom order in which a 50% deposit is required to begin production. The final payment will be due at installation. If the installation is not completed due to a service or missing product, you may pay half of the balance, and the final amount on completion.

\*\*\*Customer to remove old window treatments or other obstacles prior to installation. Any previous arrangements must be noted on this order. All free hanging verticals do not close tight. A view into the room is possible on an angle. 2" Horizontal blinds do not close tight. Light gaping will occur. This is the nature of the blind. Room darkening shades are not blackout shades unless side channels are added. With side channels there is still a possibility of light leakage.

\*\*\*No specific time of day can be promised for delivery. It is the policy of VU Window Treatments to deliver all items as quickly as possible. Unfortunately we are dependent upon our suppliers to help us meet anticipated delivery dates. Our promise of delivery is based upon deliveries to us, therefore subject to revision due to the above factors.

THIS IS A CUSTOM ORDER AND IS NOT SUBJECT TO CANCELLATION. Changes must be made within 3 days of deposit.

	\$0.00
<b>Subtotal:</b>	\$ 1,154.28
<b>Sales Tax:</b>	\$ 75.05
<b>Total:</b>	\$ 1,229.33
<b>Deposit :</b>	\$ 0.00
<b>Balance:</b>	\$ 1,229.33

### Remittance Advice

Customer: Mrs. Mabhuir Pullela  
Quotation No: VU501634  
Quotation Date: 06-05-2024  
Total Due: \$ 1,229.33  
Paid: \$

### Please detach and send with payment to:

VU Window Treatments  
301a Enterprise St  
Ocoee, Florida, 34761