



301a Enterprise St
Ocoee, Florida, 34761

Tel: 407-295-5200 Orlando
321-622-8909 Melbourne

Website: www.VUWindowTreatments.com

Quotation

Quotation No.
VU601521
Account Number
OZAE0001
Date
02-25-2025
Sales Person
Ahren

Quote To	Mrs.Carmina Ozaeta 600 E Kaley St Orlando Florida 32806 Ph: 4075385237
----------	--

Deliver To	_Ozaeta 2950 Curry Ford Rd JJ Fresh Orlando Florida 32806
------------	--

#	Location	Product	Description	Qty	Net	Total
1	din left	Roller Shades	VU Window Treatments, Mount: Outside Mount, Fabric: C-Screen Linen 5%, Color: Natural, Fascia Type: NO FASCIA, Bottom Rail Type and Color: Square Ivory, Controls: Motor RIGHT Heavy 2.5, Motorization: Arabel Motors, Motor Options: Arabel 110V Motor Any Size AM45 15, Remote Options: Arabel 6 Channel Remote White AC123 06W	1	1012.80	1,012.80
2	din right	Roller Shades	VU Window Treatments, Mount: Outside Mount, Fabric: C-Screen Linen 5%, Color: Natural, Fascia Type: NO FASCIA, Bottom Rail Type and Color: Square Ivory, Controls: Motor RIGHT Heavy 2.5, Motorization: Arabel Motors, Motor Options: Arabel 110V Motor Any Size AM45 15	1	941.48	941.48
3	din above door	Roller Shades	VU Window Treatments, Mount: Outside Mount, Fabric: C-Screen Linen 5%, Color: Natural, Fascia Type: NO FASCIA, Bottom Rail Type and Color: Square Ivory, Controls: Motor LEFT Heavy 2.5, Motorization: Arabel Motors, Motor Options: Arabel 110V Motor Any Size AM45 15	1	519.76	519.76
4		Labor/Comments	Quantity: 1, Supplier: VU Window Treatments, Charges and Comments: Labor/Trip Fee,Metal self tapping screws,6 FOOT LADDER	1	140.00	140.00

Customer Message

***This is a custom order in which a 50% deposit is required to begin production. The final payment will be due at installation. If the installation is not completed due to a service or missing product, you will be required to pay half of the balance, and the final amount on completion. ***Customer to remove old window treatments or other obstacles prior to installation. Any previous arrangements must be noted on this order. All free hanging verticals do not close tight. A view into the room is possible on an angle. 2" Horizontal blinds do not close tight. Light gaping will occur. This is the nature of the blind. Room darkening shades are not blackout shades unless side channels are added. With side channels there is still a possibility of light leakage. ***No specific time of day can be promised for delivery. It is the policy of VU Window Treatments to deliver all items as quickly as possible. Unfortunately we are dependent upon our suppliers to help us meet anticipated delivery dates. Our promise of delivery is based upon deliveries to us, therefore subject to revision due to the above factors. THIS IS A CUSTOM ORDER AND IS NOT SUBJECT TO CANCELLATION. Changes must be made within 3 days of deposit.

Subtotal : \$ 2,614.04
Sales Tax : \$ 169.91
Total : \$ 2,783.95
Deposit : \$ 0.00
Balance : \$ 2,783.95

Remittance Advice

Customer:
Quotation No: VU601521
Quotation Date: 02-25-2025
Total Due: \$ 2,783.95
Paid: \$

Please detach and send with payment to:

VU Window Treatments
301a Enterprise St
Ocoee, Florida, 34761