



301a Enterprise St
Ocoee, Florida, 34761

Tel: 407-295-5200 Orlando
321-622-8909 Melbourne

Website: www.VUWindowTreatments.com

Quotation

Quotation No.	VU602733
Account Number	LOPE0001
Date	06-09-2025
Sales Person	Ahren

Quote To	Mrs.Margarita Lopez 425 S Orange Ave Main Court House Orlando Florida 32801E Ph: 407 4024603
-----------------	--

Deliver To	Mrs.Margarita Lopez 425 S Orange Ave Main Court House Orlando Florida 32801E Ph: 407 4024603
-------------------	--

#	Location	Product	Description	Qty	Net	Total
1	LL01.08	Labor/Comments	Supplier: VU Window Treatments, Mount: Ceiling, Special Instructions: TRACK AND ROLLERS FOR RIGHT SIDE OF HALLWAY REPLACEMENT, Location: LL01.08	1	220.97	220.97
2	LL01.08	Labor/Comments	Supplier: VU Window Treatments, Mount: Ceiling, Special Instructions: EXTRA CURTIAN FOR LEFT SIDE OF HALL WAY, Location: LL01.08	1	155.97	155.97
3	LL01.08	Labor/Comments	Supplier: VU Window Treatments, Mount: Ceiling, Special Instructions: CURTIANS FOR RIGHT SIDE OF HALL WAY, Location: LL01.08	1	337.97	337.97
4	LL01.08	Labor/Comments	Supplier: VU Window Treatments, Mount: Ceiling, Special Instructions: EXTRA ROLLERS BOTH SIDES HALLWAY REPLACEMENT, Location: LL01.08	1	122.17	122.17
5		Labor/Comments	Supplier: VU Window Treatments, Charges and Comments: Labor/Trip Fee,Concrete,4 FOOT LADDER,2 INSTALLERS,Labor, Special Instructions: ADD CURTAIN TO LEFT SIDE. REPLACE TRACK AND ADD CURTAIN ON RIGHT SIDE.	1	225.00	225.00

Customer Message

***This is a custom order, all orders under \$1000 must be paid in full to begin production, all orders over \$1000 will require a 50% deposit. THE FINAL PAYMENT WILL BE DUE PRIOR TO INSTALLATION.

If the installation cannot be completed due to a service, you will be required to pay the balance minus the item to be serviced.

***Customer to remove old window treatments prior to installation, unless TAKE DOWNS are noted on the order. FURNITURE AND BREAKABLES WILL NEED TO BE MOVED PRIOR TO ARRIVAL.

***All free hanging verticals do not close tight. A view into the room is possible on an angle. 2" Horizontal blinds do not close tight. Light gaping will occur. This is the nature of the blind. Room darkening shades are not blackout shades unless side channels are added. With side channels there is still a possibility of light leakage.

***No specific time of day can be promised for delivery. It is the policy of VU Window Treatments to deliver all items as quickly as possible. Unfortunately we are dependent upon our suppliers to help us meet anticipated delivery dates. Our promise of delivery is based upon deliveries to us, therefore subject to revision due to the above factors.

***THIS IS A CUSTOM ORDER AND CAN ONLY BE CANCELLED WITHIN 3 DAYS OF DEPOSIT. The details on the order are final once in production. If you do not understand the terminology of the products selected, please ask your sales advisor.

Changes must be made within 3 days of deposit. QUOTES ARE VAILD FOR 30 DAYS.

Subtotal : \$ 1,062.08

Sales Tax : \$ 0.00

Total : \$ 1,062.08

Deposit : \$ 0.00

Balance : \$ 1,062.08

Remittance Advice

Customer:

Quotation No: VU602733

Quotation Date: 06-09-2025

Total Due: \$ 1,062.08

Paid:

\$

Please detach and send with payment to:

VU Window Treatments

301a Enterprise St

Ocoee, Florida, 34761