



301a Enterprise St  
Ocoee, Florida, 34761

Tel: 407-295-5200 Orlando  
321-622-8909 Melbourne

Website: [www.VUWindowTreatments.com](http://www.VUWindowTreatments.com)

## Quotation

Quotation No.	VU603877
Account Number	HAIR0001
Date	09-18-2025
Sales Person	Ahren

Quote To	Mrs.Sophia Hairston 2746 Fiddle Leaf Loop Apopka Florida 32712 Ph: 9176260785
----------	---

Deliver To	Mrs.Sophia Hairston 2746 Fiddle Leaf Loop Apopka Florida 32712 Ph: 9176260785
------------	---

#	Location	Product	Description	Qty	Net	Total
1	slider	Artisan Drapes	Supplier: Artisan Window Fashions, Product Type: Drapes 3, Type: Ripple Fold, Mount: Ceiling, Special Instructions: BATTERY MOTOR tactus-06 fabric SPLIT STACK, Liner Type_Color: NO LINER, Stack: Artisan Motor Left, Track: Ceiling Mounted Reg Profile, Finish: White, Extras: Artisan Single Channel Remote	1	4182.10	4,182.10
2	liv wall	Artisan Drapes	Supplier: Artisan Window Fashions, Product Type: Drapes 3, Type: Ripple Fold, Mount: Ceiling, Special Instructions: BATTERY MOTOR TACTUS -06 FABRIC STACK LEFT, Stack: Artisan Motor Left, Track: Ceiling Mounted Reg Profile, Finish: White, Extras: Artisan Single Channel Remote	1	2293.20	2,293.20
3		NOTES	NOTES: Add \$488 per drape for lining.	1	0.00	
4		Labor/Comments	Supplier: VU Window Treatments, LADDER: 4 FOOT LADDER, Labor and Trip Fees: Labor/Trip Fee	2	125.00	250.00

### Customer Message

\*\*\*This is a custom order, all orders under \$1000 must be paid in full to begin production, all orders over \$1000 will require a 50% deposit. THE FINAL PAYMENT WILL BE DUE PRIOR TO INSTALLATION.

If the installation cannot be completed due to a service, you will be required to pay the balance minus the item to be serviced.

\*\*\*Customer to remove old window treatments prior to installation, unless TAKE DOWNS are noted on the order. FURNITURE AND BREAKABLES WILL NEED TO BE MOVED PRIOR TO ARRIVAL.

\*\*\*All free hanging verticals do not close tight. A view into the room is possible on an angle. 2" Horizontal blinds do not close tight. Light gaping will occur. This is the nature of the blind. Room darkening shades are not blackout shades unless side channels are added. With side channels there is still a possibility of light leakage. OVERSIZED shutter panels may require them to be lifted into the window due to size.

\*\*\*No specific time of day can be promised for delivery. It is the policy of VU Window Treatments to deliver all items as quickly as possible. Unfortunately we are dependent upon our suppliers to help us meet anticipated delivery dates. Our promise of delivery is based upon deliveries to us, therefore subject to revision due to the above factors.

\*\*\*THIS IS A CUSTOM ORDER AND CAN ONLY BE CANCELLED WITHIN 3 DAYS OF DEPOSIT. The details on the order are final once in production. If you do not understand the terminology of the products selected, please ask your sales advisor.

Changes must be made within 3 days of deposit. QUOTES ARE VAILD FOR 30 DAYS.

Subtotal : \$ 6,725.30

Sales Tax : \$ 437.15

Total : \$ 7,162.45

Deposit : \$ 0.00

Balance : \$ 7,162.45

### Remittance Advice

Customer:

Quotation No: VU603877

Quotation Date: 09-18-2025

Total Due: \$ 7,162.45

Paid:

\$

Please detach and send with payment to:

VU Window Treatments

301a Enterprise St

Ocoee, Florida, 34761