



301a Enterprise St
Ocoee, Florida, 34761

Tel: 407-295-5200 Orlando
321-622-8909 Melbourne

Website: www.VUWindowTreatments.com

Quotation

Quotation No.
VU604420
Account Number
CANC0001
Date
11-18-2025
Sales Person
Ahren

Quote To	Mrs.Annette Cancel 6225 Riverfront Ct Blvd Titusville Florida 32780 Ph: 4072426076
----------	--

Deliver To	Mrs.Annette Cancel 6225 Riverfront Ct Blvd Titusville Florida 32780 Ph: 4072426076
------------	--

#	Location	Product	Description	Qty	Net	Total
1	lobby up left	Roller Shades	VU Window Treatments, Mount: Outside Mount, Fabric: 3% Sunshade, Color: White + Grey, Fascia Type: NO FASCIA, Bottom Rail Type and Color: Square Grey, Controls: HEAVY Clutch Left, Reverse Roll and Railroad: REVERSE ROLL, Special Instructions: 67 67 48	1	698.00	698.00
2	lobby up right	Roller Shades	VU Window Treatments, Mount: Outside Mount, Fabric: 3% Sunshade, Color: White + Grey, Fascia Type: NO FASCIA, Bottom Rail Type and Color: Square Grey, Controls: HEAVY Clutch Right, Reverse Roll and Railroad: REVERSE ROLL	1	698.00	698.00
3		Labor/Comments	Supplier: VU Window Treatments, WALL MATERIAL: METAL DRILL BIT OR SELF TAPPING SCREWS NEEDED, Labor and Trip Fees: Labor/Trip Fee,TRIP OVER 30 MILES,2 INSTALLERS	1	230.00	230.00
4		Labor/Comments	Supplier: VU Window Treatments, LADDER: MOTORIZED LIFT RENTAL, Labor and Trip Fees: Labor/Trip Fee	1	625.00	625.00

Customer Message

***This is a custom order, all orders under \$1000 must be paid in full to begin production, all orders over \$1000 will require a 50% deposit. THE FINAL PAYMENT WILL BE DUE PRIOR TO INSTALLATION. If the installation cannot be completed due to a service, you will be required to pay the balance minus the item to be serviced.

***Customer to remove old window treatments prior to installation, unless TAKE DOWNS are noted on the order. FURNITURE AND BREAKABLES WILL NEED TO BE MOVED PRIOR TO ARRIVAL.

***All free hanging verticals do not close tight. A view into the room is possible on an angle. 2" Horizontal blinds do not close tight. Light gaping will occur. This is the nature of the blind. Room darkening shades are not blackout shades unless side channels are added. With side channels there is still a possibility of light leakage. OVERSIZED shutter panels may require them to be lifted into the window due to size. LARGE roller shades have a tendency to have ripples in the fabric. This is normal.

***No specific time of day can be promised for delivery. It is the policy of VU Window Treatments to deliver all items as quickly as possible. Unfortunately we are dependent upon our suppliers to help us meet anticipated delivery dates. Our promise of delivery is based upon deliveries to us, therefore subject to revision due to the above factors.

***THIS IS A CUSTOM ORDER AND CAN ONLY BE CANCELLED WITHIN 3 DAYS OF DEPOSIT. The details on the order are final once in production. If you do not understand the terminology of the products selected, please ask your sales advisor.

Changes must be made within 3 days of deposit. QUOTES ARE VAILD FOR 30 DAYS.

Subtotal : \$ 2,251.00

Sales Tax : \$ 0.00

Total : \$ 2,251.00

Deposit : \$ 0.00

Balance : \$ 2,251.00

Remittance Advice

Customer:

Quotation No: VU604420

Quotation Date: 11-18-2025

Total Due: \$ 2,251.00

Paid: \$

Please detach and send with payment to:

VU Window Treatments
301a Enterprise St
Ocoee, Florida, 34761