



301a Enterprise St
Ocoee, Florida, 34761

Tel: 407-295-5200 Orlando

321-622-8909 Melbourne

Website: www.VUWindowTreatments.com

Order Confirmation

Job Number
VU604561
Account Number
VACH0001
Order Date
12-08-2025
Sales Person
Ahren
Customer Reference

Quote To	Mrs. AnnMarie Vachala 19073 Sabal St Orlando 32833 Ph: 9543033344 Email: avachala13@yahoo.com
----------	---

Deliver To	Mrs. AnnMarie Vachala 19073 Sabal St Orlando Florida 32833 Ph: 9543033344
------------	---

#	Location	Product	Description	Qty	Net	Total
1	BED 3 MOMS ROOM	Roller Shades	Supplier: VU Window Treatments, Motorization: Top Motor, Motor Options: TOP 1.5nM Motor RF and Bluetooth USB C, Remote Options: TOP 5 Channel Remote RF, Accessories: TOP Charger Cable USB C 4m with USB BLOCK	1	250.90	250.90
2		NOTES	NOTES: YOU WILL NEED THE PROPER BRACKETS FOR THE MOTOR it is currently fascia with chain., Notes_	1	0.00	
3		NOTES	NOTES: PLEASE INSTALL THE P CLIP THAT WAS MISSED ON INSTALL, Notes_	1	0.00	
4	MASTER BATH	Roller Shades	Supplier: VU Window Treatments, Motorization: Top Motor, Motor Options: TOP 1.5nM Motor RF and Bluetooth USB C, Remote Options: TOP 5 Channel Remote RF, Accessories: TOP Charger Cable USB C 4m with USB BLOCK	1	250.90	250.90

Customer Message
<p>***This is a custom order, all orders under \$1000 must be paid in full to begin production, all orders over \$1000 will require a 50% deposit. THE FINAL PAYMENT WILL BE DUE PRIOR TO INSTALLATION. If the installation cannot be completed due to a service, you will be required to pay the balance minus the item to be serviced.</p> <p>***Customer to remove old window treatments prior to installation, unless TAKE DOWNS are noted on the order. FURNITURE AND BREAKABLES WILL NEED TO BE MOVED PRIOR TO ARRIVAL.</p> <p>***All free hanging verticals do not close tight. A view into the room is possible on an angle. 2" Horizontal blinds do not close tight. Light gaping will occur. This is the nature of the blind. Room darkening shades are not blackout shades unless side channels are added. With side channels there is still a possibility of light leakage. OVERSIZED shutter panels may require them to be lifted into the window due to size. LARGE roller shades have a tendency to have ripples in the fabric. This is normal.</p> <p>***No specific time of day can be promised for delivery. It is the policy of VU Window Treatments to deliver all items as quickly as possible. Unfortunately we are dependent upon our suppliers to help us meet anticipated delivery dates. Our promise of delivery is based upon deliveries to us, therefore subject to revision due to the above factors.</p> <p>***THIS IS A CUSTOM ORDER AND CAN ONLY BE CANCELLED WITHIN 3 DAYS OF DEPOSIT. The details on the order are final once in production. If you do not understand the terminology of the products selected, please ask your sales advisor.</p> <p>Changes must be made within 3 days of deposit. QUOTES ARE VALID FOR 30 DAYS.</p>

Discount :	\$ 100.36
Subtotal :	\$ 401.44
Sales Tax :	\$ 26.09
Total :	\$ 427.53

Payment : \$ 0.00

Balance Due : \$ 427.53

Installed by:

Date:

Remittance Advice

Customer:
Quotation No: VU604561
Quotation Date: 12-06-2025
Total Due: \$ 427.53
Paid: \$

Please detach and send with payment to:

VU Window Treatments
301a Enterprise St
Ocoee, Florida, 34761